

Certificate of Compliance

Certificate: 1923635 (LR 112669)

Project: 1985548

S.I.T. Controls U.S.A. Inc. Issued to: 900-J Center Park Dr Charlotte, NC 28217 USA **Attention: Andrew Pepin**

Master Contract: 189456

Date Issued:

2007/12/12

The products listed below are eligible to bear the CSA Mark shown with adjacent indicators 'C' and 'US'



Issued by:

Valdis Udris

Authorized by: Trevor Perera, Manager of Certification Services

Trever Perera

PRODUCTS

- SYSTEMS (GAS) - Automatic Ignition and Components-Certified to U.S. CLASS 3335 81 Standards

- SYSTEMS (GAS) - Automatic Ignition and Components CLASS 3335 01

Model Number

Interrupted Spark Ignition Systems

0.584.3(01-99)

The 'C' and 'US' indicators adjacent to the CSA Mark signify that the product has been evaluated to the applicable CSA and ANSI/UL Standards, for use in Canada and the U.S., respectively. This 'US' indicator includes products eligible to bear the 'NRTL' indicator. NRTL, i.e. National Recognized Testing Laboratory, is a designation granted by the U.S. Occupational Safety and Health Administration (OSHA) to laboratorics which have been recognized to perform certification to U.S. Standards.

DQD 507 Rev. 2004-06-30



Certificate:	1923635 (LR 112669)	Master Contract:	189456
Project:	1985548	Date Issued:	2007/12/12

APPLICABLE REQUIREMENTS

CAN/CSA-C22.2 No. 199-M89 (R2004)	Combustion Safety Controls and Solid-State Igniters for Gas-
	and Oil-Burning Equipment

ANSI Z21.20-2005 Automatic Gas Ignition Systems and Components

MARKINGS

All markings in compliance with the applicable requirements are found on descriptive report page 2.



Supplement to Certificate of Compliance

Certificate: 1923635

Master Contract: 189456

The products listed, including the latest revision described below, are eligible to be marked in accordance with the referenced Certificate.

Product Certification History

Project	Date	Description
1985548	2007/12/12	Minor circuit changes, Revised drawings.
1923635	2007/10/16	Original certification of model 0.584.3(01-99).

History

Supplement Notes